


Tech Bulletin

Steam Hose Chart

The chart below represents the three forms of water when subjected to heat and pressure. The red line represents the point at which hot water becomes saturated steam. The area above the line is superheated steam.

Gauge Pressure (PSI)	Temperature of Saturated Steam (°F)
0	212
10	239
25	267
50	298
75	320
100	338
125	353
150	366
175	377
200	388
225	397
250	406



Use only hoses specifically designed for the application. Contact Parker Industrial Hose at (866) 810-HOSE for specific product recommendations.

Parker Hannifin Corporation
 Industrial Hose Division
 17295 Foltz Industrial Pkwy
 Strongsville, OH 44149
 Telephone: (440) 268-2120
 Fax: (440) 268-2230
www.safehose.com